



ITTEST

QUESTION & ANSWER

Guías de estudio precisos, Alta tasa de paso!



Ittest ofrece información actualizada de forma gratuita en un año!

<http://www.ittest.es/>

Exam : **HP2-T23**

Title : Supporting Industry
Standard Server Solutions

Version : DEMO

and encryption keys on a DL380 G7.

Which action must a field engineer perform before upgrading server firmware and installing an additional storage controller?

- A.Create new certificates and encryption keys.
- B.Disable BitLocker.
- C.Delete certificates and encryption keys.
- D.Disable TPM.

Answer: B

6.What is the name of the HP agent that enables a customer to manage HP software that is stored in a user-defined repository?

- A.Web-Based Enterprise Management (WBEM)
- B.Version Control Repository Manager (VCRM)
- C.Version Control Agent
- D.Data Collection Reports

Answer: B

Reference:http://h20565.www2.hp.com/portal/site/hpsc/template.BINARYPORTLET/public/kb/docDisplay/resource.process/?spf_p.tpst=kbDocDisplay_ws_BI&spf_p.rid_kbDocDisplay=docDisplayResURL&javax.portlet.begCacheTok=com.vignette.cachetoken&spf_p.rst_kbDocDisplay=wsrresourceState%3DdocId%253Demr_na-c031689542%257CdocLocale%253Den_US&javax.portlet.endCacheTok=com.vignette.cachetoken(page 20, see HP version control repository manager)

7.What happens if you lose or misplace a Trusted Platform Module (TPM) key?

- A.The system requests the Administrator password.
- B.The system enters diagnostic mode.
- C.The system will not boot.
- D.Data loss might occur.

Answer: D

8.An engineer is installing an HP R7000 UPS and an Extended Runtime Module (ERM) in an existing HP 10642 G2 rack.This rack contains 10 ProLiant DL380e Gen8 servers mounted from 1U upward.

How should the engineer perform this installation?

- A.Mount the R7000 UPS at 10U in the 10642 G2 rack with the ERM on top of the R7000 UPS.
- B.Remove the lowest ProLiant DL380e Gen8 servers and mount the R7000 and the ERM at the lowest position in the rack.Mount the removed ProLiant DL380e Gen8 servers at a higher position in the 10642 G2 rack.
- C.Mount the R7000 at the highest position possible in the 10642 G2 rack with the ERM just below the UPS.
- D.Remove the two lowest mounted ProLiant DL380e Gen8 servers and mount the R7000 at the bottom of the 10642 G2 rack.Mount the two removed ProLiant DL380e Gen8 servers at the top of the 10642 G2 rack.Mount the ERM above the remaining original mounted ProLiant DL380e Gen8 servers.

Answer: B

9.Which RAID level is known as Advance Data Guarding (ADG)?

- A.RAID 1
- B.RAID 5
- C.RAID 6
- D.RAID 10

Answer: C

Reference:<http://h50146.www5.hp.com/products/storage/whitepaper/pdfs/c00386950.pdf>

10.Which HP utility can patch a ProLiant server with a release set made up of drivers, firmware, and software that have been tested together?

- A.HP Smart Update Firmware DVD
- B.HP Version Control Update (VCU)
- C.Integrated Lights Out (iLO)
- D.Service Pack for ProLiant (SPP)

Answer: D